



GOOSENECK MOLDINGS

Step One




Flush trim with Amana Tool no.47126-2

Step Two




Shape cove with Amana Tool no.45949
Use light cuts

Step Three



Shape ogee with Amana Tool no.54124

Step Four



Shape roundover with "roundunder" bit Amana Tool no.57138

Step Five



Bandsaw outside curve to complete molding